

FIELD INSPECTION

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant
Inspection Date:	Thursday, January 10, 2019	Project Contact:	Brian Clauto
Spread: Montgomery County MP228-231	Spread H	Weather (Wet/Dry/Rain):	Dry

STAGE OF CONSTRUCTION: (Check all that apply)

- ☐ Clearing

☐ Rough Grading

☐ Trench Excavation

☐ Pipe Assembly, Testing & Installation

☐ Backfilling and Grade Restoration

☐ Final Grading & Stabilization

☒ Other: dormant

- | | | Yes | No | N/A |
|---|---|-------------------------------------|-------------------------------------|--------------------------|
| 1 | Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans? | <input checked="" type="checkbox"/> | <input type="checkbox"/> | <input type="checkbox"/> |
| 2 | Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| 3 | Areas of offsite sediment deposition were observed? | <input type="checkbox"/> | <input checked="" type="checkbox"/> | <input type="checkbox"/> |

Comments:

- MP 229 St#12132+91 CFS is torn and bridge crossing near designated stream SC-29
- MP 231 St#12235+92 area has been stabilized.
- MP 228 St#12072+84 area has been stabilized.
- MP 230 St#12152+00 area has been stabilized
- ECD are in place and functioning at designated streams SMM-11, SMM-13, SF-16

Recommended Corrective Action: Maintain all controls per the approved plan and annual standards and specs.

Deadline: Within 24hr notification

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature:  Date: 2-12-19

FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 10, 2019

- Fig. 1 CFS at st#12132+91 is torn at bridge crossing



- Fig. 2 Designated stream SC-29 controls in place and functioning



- Fig. 3 Aquatic resource at ST#12132+00 repairs have been made and controls in place and functioning.



- Fig. 4 Aquatic resource at ST#12132+00 repairs have been made and controls in place and functioning.



FIELD INSPECTION PHOTO LOG

Project Name: Mountain Valley Pipeline

Date: Thursday, January 10, 2019

- Fig. 5 MP 228 St#12072+84 area has been stabilized



- Fig. 6 ECD are in place and functioning at designated stream SMM-13



- Fig. 7 ECD are in place and functioning at designated stream SF-16



- Fig. 8 MP230 St#12152+00 area has been stabilized

